


Clean Fittings

Male NPT Connector H- MC

H = Clean fitting



| Part No. | ZCR Size | d | | L | | H | P NPT | Working Pressure psig (bar) | | |
|-------------|----------|-------|------|------|------|-------|-------|----------------------------------|----------------|---------------|
| | | mm | in. | mm | in. | | | NI | SS | CU |
| H-ZMC 2- 1N | 1/8 | 2.30 | 0.09 | 27.2 | 1.07 | 3/8 | 1/16 | 9000 (620) 7200 (496) | | |
| H-ZMC 2- 2N | | | | | | | | | | |
| H-ZMC 4- 2N | 1/4 | 4.55 | 0.18 | 33.3 | 1.31 | 5/8 | 1/8 | 8000 (551) | 10000 (689) | 6400 (440) |
| H-ZMC 4- 4N | | | | | | | | | | |
| H-ZMC 8- 6N | 1/2 | 9.65 | 0.38 | 41.9 | 1.65 | 15/16 | 3/8 | 3500 (241) | 4300 (296) | 2800 (192) |
| H-ZMC 8- 8N | | | | | | | | | | |
| H-ZMC12-12N | 3/4 | 15.70 | 0.62 | 55.6 | 2.19 | 1 5/8 | 3/4 | 3000 (206) | 3700 (254) | 2400 (165) |
| H-ZMC16-16N | 1 | 22.10 | 0.87 | 62.7 | 2.47 | | 1 | 2400 (165) | 3000 (206) | 1900 (130) |